

FIG. 1




FIG. 3




FIG. 3




FIG. 4

FIG. 5




FIG. 5

FIG. 6





FIG. 6

FIG. 7



**DIGI-DATA PC Controller** 3:12pm

---

**Digi Data Job: Job**

**Select Job:** [01007] **Clear**

**Add Job:** **Print**

**Measure:**

☒ Damaged vehicle

☐ Required vehicle

**Start Recording**

---

**Vehicle:** Nissan Maxima **Reg No:** NIS 001 **Client:** Mr G. Fellows **Date:** 19 Aug 98 **File:** X-487

---

**Active Quadrant:** ☒ A ☐ B ☐ C ☐ D

**Measurement Method:** ☒ Vehicle Data ☐ Comparison **Unit:** mm

---

	Vehicle Data				Damaged		Required	
	Ref	D/S	P/S	D/S	P/S	D/S	P/S	
Datum Height at Cross Bar	[203]							
Width	[G]	[1300]	[0]					
Length	[C]	[970]	[970]					
Height	[C]	[370]	[370]					
Diagonal - 1	[C]	[1486]	[1486]					

---

**Comment:** Driver side front tyre badly worn.

**Close**

---

**Digi Data Group** **DIGI-DATA PC Controller**

FIG.8

## VEHICLE MEASUREMENT REPORT

	VEHICLE _____	DATE: _____
	REG NO: _____	JOB: _____
	CLIENT: _____	FILE: _____

DATUM HEIGHT AT CROSS BAR	203	A	VEH.DATA		DAMAGED		REPAIRED	
		REF	D/S	P/S	D/S	P/S	D/S	P/S
WIDTH		O	1200		0		0	
LENGTH		C	970	970	-15	0	-1	0
HEIGHT		C	370	370	-7	-1	-1	-1
DIAGONAL		C	1486	1486	-8	0	-1	0

COMMENTS: Driver side front tyre badly worn.

DATUM HEIGHT AT CROSS BAR	B	VEH.DATA		DAMAGED		REPAIRED		
		REF	D/S	P/S	D/S	P/S	D/S	P/S
WIDTH								
LENGTH								
HEIGHT								
DIAGONAL								


COMMENTS:

DATUM HEIGHT AT CROSS BAR	C	VEH.DATA		DAMAGED		REPAIRED		
		REF	D/S	P/S	D/S	P/S	D/S	P/S
WIDTH								
LENGTH								
HEIGHT								
DIAGONAL								

COMMENTS:

DATUM HEIGHT AT CROSS BAR	D	VEH.DATA		DAMAGED		REPAIRED	
		REF	D/S	P/S	D/S	P/S	D/S
WIDTH	A	1478		0		0	
LENGTH	B	844	844	-22	0	0	0
HEIGHT	C			89	89	89	89
DIAGONAL	D	1662	1662	-11	0	-1	0

COMMENTS:



Operator: \_\_\_\_\_

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

FIG.9